

- ii. The property owner or resident shall be responsible for blockages and the clearing of blockages within a sewer service pipe to the sewer main line.
- iii. If the blockage is within the sewer service pipe then the attending staff member shall advise the resident or property owner of such. Staff may, upon the request of the resident or property owner, provide a manual sewer snake for the resident or property owner to use at their own risk.

d. Sewer Service Line Structural Failure

- i. The Town of Carstairs will as soon as reasonably practical review the circumstances of the structural failure and determine if repairs are needed.

e. Liability

- i. Pursuant to the provisions of the Municipal Government Act and amendments thereto, the Town will neither admit to, nor be held liable for, any direct or indirect damages to property as a result of the operation or non operation of the sewer system.

End of Policy